



VERSION HISTORY FIRMWARE TP150/180

TT 170/210

© Fronius International GmbH

Version 00000 2020/2021 00000

BU Perfect Welding

Fronius reserves all rights, in particular rights of reproduction, distribution and translation.

No part of this work may be reproduced in any way without the written consent of Fronius. It must not be saved, edited, reproduced or distributed using any electrical or electronic system.

You are hereby reminded that the information published in this document, despite exercising the greatest of care in its preparation, is subject to change and that neither the author nor Fronius can accept any legal liability.

Gender-specific wording refers equally to female and male form.

TABLE OF CONTENT

1	CHANGES FROM v4.0.34 TO v4.1.7	4
1.1	Features TP 150/180	4
1.2	Features TT 170/210	4
2	CHANGES FROM V1.7.17 TO V4.0.34	4
2.1	Features TP 150/180	4
2.2	Features TT 170/210	4
3	CHANGES FROM V1.7.15 TO V1.7.17	5
3.1	Features.....	5
4	CHANGES FROM V1.5.4 TO V1.7.15	5
4.1	Features.....	5
5	CHANGES FROM V1.4.6 TO V1.5.4	6
5.1	Features.....	6
6	CHANGES FROM V1.4.5 TO V1.4.6	6
6.1	Features.....	6
7	CHANGES FROM V1.3.10 TO V1.4.5	6
7.1	Features.....	6
8	CHANGES FROM V1.2.11 TO V1.3.10	7
8.1	Features.....	7

1 CHANGES FROM V4.0.34 TO V4.1.7

Date: February 2021

1.1 Features TP 150/180

- / Use of new PWT Service Tool (changed naming)

1.2 Features TT 170/210

- / Implementation of EHF (External HF) parameter for easier calibration
- / Change of start and stop in case of stop welding mode (adapted to TT/MW 230i)
- / Use of new PWT Service Tool (changed naming)
- / Internal Bug-fixing (Gas valve)

2 CHANGES FROM V1.7.17 TO V4.0.34

Date: September 2020

ATTENTION - MERGING THE SOFTWARE OF TRANSPOCKET 150/180 & TRANSTIG 170/210!

ATTENTION DOWNGRADE LOCK FOR ALL SUBSEQUENT VERSIONS –

DO NOT DOWNGRADE FROM V4.0.34

- / From now on there is only one software version for the TP 150/180 & TT170/210 starting with v4.0.31
- / There is no change in the update process - ServiceTool has already been extended by TT170/210

2.1 Features TP 150/180

- / Implementation foot remote control RC pedal/TIG TMC 5m (for RC & TIG variant)
- / Support new TIG torches with Poti control (for RC & TIG variant)
- / Implementation Gas Purging
- / Fix TIG torch LED control (only applies to TIG version)
- / Internal bug-fixing (Errorlog, E02 filtering)

2.2 Features TT 170/210

- / Implementation of TouchHF function in parameter "HF" - selection "on", "off", tHf
- / Support new TIG torches with Poti control

- / Bugfix TIG pulse noise
- / ServiceTool Support for BPS1800 HW Prints (TP Hotwire Variant)
- / Remedy TIG torch LED control
- / Internal bug-fixing (Errorlog, E02 filtering)

3 CHANGES FROM V1.7.15 TO V1.7.17

Datum: March 2019

3.1 Features

- / Bugfix – Logbook changes → Display of E10 / E17 & Display Freeze possible

**ATTENTION DOWNGRADE LOCK VERSIONS – DO NOT
DOWNGRADE FROM V1.7.17**

4 CHANGES FROM V1.5.4 TO V1.7.15

Date: January 2019

4.1 Features

**ATTENTION DOWNGRADE-LOCK – DO NOT PERFORM A DOWNGRADE
FROM V1.7.15 TO V1.5.4**

If a downgrade is necessary in exceptional cases - please use the previous version of ServiceTool2 and downgrade to v1.4.6 - then you can upgrade to e.g. v1.5.4 again – in case of questions contact service.

- / New Desktop Software „ServiceTool2_V2“ available - **no downgrade possible any more**
 - please just use the new ServiceTool anymore
- / Implementation minus temperature - the machines are working now at a temperature of around -20deg
- / Bugfix – improvement for “display freeze” problem
- / Bugfix – puls current display in 2-step / 4-step mode
- / Change in TIG mode setting – UCO parameter can now also be adjusted when “CSS” and “TRI” are not set to OFF

5 CHANGES FROM V1.4.6 TO V1.5.4

Date: November 2017

5.1 Features

- / New desktop software „ServiceTool2“(no live values anymore and bug fixing)
- / Bug fixing - TIG mode in 2-step & 4-step mode
- / further (internal) bug fixing



6 CHANGES FROM V1.4.5 TO V1.4.6

Date: June 2017

6.1 Features


- / Internal process control adjusted
- / Bug fixing

7 CHANGES FROM V1.3.10 TO V1.4.5

Date: March 2017

7.1 Features

- / Implementation of
 - TIG variants
 - TIG Pulsing & TAC
 - STICK Pulsing



E-Hand Pulsen

- / verbesserte Schweißeigenschaften bei Zwangslagen
- / sehr gut geeignet beim Wurzelschweißen
- / universell einsetzbarer Puls Mode
- / besserer Spaltüberbrückbarkeit
- / sehr gut geeignet für Steignahtschweißen
- / feinschuppige Nahtoptik

/ New version of the desktop software „Service Tool“

/ Bug fixing


8 CHANGES FROM V1.2.11 TO V1.3.10

Date: November 2016

8.1 Features

/ Implementation of the parameter „str“(start ramp) to change the current ramp during the ignition.

Factory setting - ON (activated ramp)



“Str” Start-ramp parameter

- Str**
- ignition behaviour adjusted to customer
- / Adjustable ignition
 - / with the Str parameter the start ramp of the machine can be set / adjusted
 - / though there is a customized ignition behaviour depending on the need of the customer
 - / Str ON – optimized; Str OFF – direct current rise

/ Implementation of the new TP 150/180 RC (Remote Control) variants

/ Bug fixing